





# Embankment Failure



Bear Creek is migrating into the roadway embankment for Avondale Road.

# Embankment Settling Under Sidewalk





# *Embankment Failure*



The embankment, with two stormwater outfalls and a utility pole, is being eroded by Bear Creek.



# Stormwater Outfall Damage

2010



2017

